



Case Study

Brighton Hospital

Unit reference

Theatre AHU

Scope of works:

Direct drive fan upgrade

(High pressure system) – Coastal environment

The existing belt driven fan was found to have heavy corrosion on the fan blades, corroded inlet damper and fan section located within a coastal environment.

A high-pressure AC plug fan was installed, along with a replacement stainless steel damper, bulkheads, corrosion treatment and stainless-steel flooring. Works completed over a weekend.

Contact us

Unit 7 Stag Business Park,
164/166 Christchurch Road,
Ringwood, Hampshire,
BH24 3AS

Telephone:
01425 475384

Email:
sales@ahs-ss.uk.com


www.ahs-ss.uk.com

ahs  TM
(Specialist Services) Ltd

Case Study

Brighton Hospital Theatre AHU

Before Upgrade



Completed Upgrade

