



Case Study

## Hospital

Unit reference

Toilet extract twin fan

Scope of works:

Replaced failed fans with direct drive EC fans,  
new auto changeover panel, new roof

**The original units' fans had failed, along with the roof becoming damaged and being held in place by a paving slab.**

Due to budgetary constraints, the customer could not afford the cost of a full replacement and on inspection of the original casework, a solution to upgrade the fans and installing a replacement roof was proposed to fit the customer's budget.

### Contact us

Unit 7 Stag Business Park,  
164/166 Christchurch Road,  
Ringwood, Hampshire,  
BH24 3AS

Telephone:  
01425 475384

Email:  
[sales@ahs-ss.uk.com](mailto:sales@ahs-ss.uk.com)

Case Study

## Hospital

Toilet extract twin fan

### Before Upgrade



### After Upgrade

